

Firmware Historie / History TR640/TR660IP

updated: 2024-04-17 / sm

Inhaltsverzeichnis / Table of contents

1 Firmware Historie (Deutsch).....	1
Firmware 12760-1400-08 (2024-04-17)	1
Firmware 12760-1400-07 (2023-01-17)	1
Firmware 12760-1400-06 (2022-12-09)	1
Firmware 12760-1400-05 (2021-04-21)	1
Firmware 12760-1400-04 (2020-10-27)	2
Firmware 12760-1400-03 (2020-07-14)	2
Firmware 12760-1400-02 (2020-05-20)	2
Firmware 12760-1400-01 (2019-10-15)	2
Firmware 12760-1400-00 (2019-09-24)	2
2 Firmware history (english)	2
Firmware 12760-1400-08 (2024-04-17)	2
Firmware 12760-1400-07 (2023-01-17)	2
Firmware 12760-1400-06 (2022-12-09)	2
Firmware 12760-1400-05 (2021-04-21)	2
Firmware 12760-1400-04 (2020-10-27)	2
Firmware 12760-1400-03 (2020-07-14)	2
Firmware 12760-1400-02 (2020-05-20)	2
Firmware 12760-1400-01 (2019-10-15)	2
Firmware 12760-1400-00 (2019-09-24)	2

1 Firmware Historie (Deutsch)

Firmware 12760-1400-08 (2024-04-17)

Bugfix (Display Reset).

Firmware 12760-1400-07 (2023-01-17)

Zyklischer Relaistest hat trotz Deaktivierung einen Durchlauf abgearbeitet.

Firmware 12760-1400-06 (2022-12-09)

Alarmauswertung „2 aus X“ => keine Auslösung mehr bei Sensorfehler.
 Menü im Display um Netzwerkparameter (Gateway, DNS-Server und MAC-Adresse) ergänzt.
 Bugfix (Webseite, XML)

Firmware 12760-1400-05 (2021-04-21)

Bugfix Firmware- Update

Firmware 12760-1400-04 (2020-10-27)

Bugfix Import von Konfigurations-Dateien

Firmware 12760-1400-03 (2020-07-14)

Benutzerfreundlichkeit am Gerät und auf Webseite verbessert,
Alarmauswertung (Verzögerungszeiten) optimiert,
DHCP Eindeutige ID = MAC-Nr.

Firmware 12760-1400-02 (2020-05-20)

Kompatibilitätsverbesserungen

Firmware 12760-1400-01 (2019-10-15)

Änderung an Kommunikation mit Echtzeituhr

Firmware 12760-1400-00 (2019-09-24)

Erste Freigabe

2 Firmware history (english)

Firmware 12760-1400-08 (2024-04-17)

Bug fix (Display reset).

Firmware 12760-1400-07 (2023-01-17)

Cyclic relay test has processed one run despite deactivation.

Firmware 12760-1400-06 (2022-12-09)

Alarm evaluation „2 of X“ => no more triggering in case of sensor error.
Network parameters (gateway, DNS server, MAC address) added to the display menu.
Bug fix (website, XML)

Firmware 12760-1400-05 (2021-04-21)

Bugfix Firmware- Update

Firmware 12760-1400-04 (2020-10-27)

Bugfix Import from configuration- files

Firmware 12760-1400-03 (2020-07-14)

Improved usability on the device and on the website,
Optimized alarm evaluation (delay times),
DHCP Unique ID = MAC no.

Firmware 12760-1400-02 (2020-05-20)

Compatibility improvements

Firmware 12760-1400-01 (2019-10-15)

Changes at communication with Real Time Clock

Firmware 12760-1400-00 (2019-09-24)

First release