

Firmware Historie / History für UR840IP / UR420IP/ UR420IP

updated: 2024-04-16 / sm

Inhaltsverzeichnis / Table of contents

1 Firmware Historie (Deutsch).....	2
Firmware 12820-1402-00.....	2
2 Firmware history (english)	3
Firmware 12820-1402-00.....	3

1 Firmware Historie (Deutsch)



Nach einem Firmwareupdate kann es zu Darstellungsfehlern im Webbrowser kommen!
Mit der Tastenkombination [STRG] + [F5] wird der Cache im Webbrowser gelöscht und die Webseite korrekt angezeigt.

ACHTUNG:

- Programme sind nicht Bestandteil der Firmware und müssen getrennt installiert/aktualisiert werden
- Firmwareupdates haben keinen Einfluss auf durchgeführte Schutzprüfungen

Firmware 12820-1402-00

Erste Freigabe.

2 Firmware history (english)



**After a firmware update, display errors may occur in the web browser!
With the key combination [CTRL] + [F5] the cache in the web browser is cleared
and the web page is displayed correctly.**

ATTENTION:

- Programmes are not part of the firmware and must be installed/updated separately.
- Firmware updates have no influence on performed protection tests.

Firmware 12820-1402-00

First release.